



- NOTES:**
- INDICATES LIMITS OF PARTIAL DEPTH CONCRETE REPAIR AREA.
 - INDICATES LIMITS OF TRANSITION AREA FROM NEW MSW CONCRETE OVERLAY TO EXISTING MSW CONC. SLAB.

CONNECTICUT RESOURCES RECOVERY AUTHORITY
 TEL. NO. (860)-757-7700
 FAX. NO. (860)-757-7742

NOT FOR CONSTRUCTION

A&E FIRM
URS
 URS CORPORATION AES
 500 ENTERPRISE DRIVE
 ROCKY HILL, CT. 06067
 1-(860)-529-8882

A&E SEAL

THE INFORMATION CONTAINED IN THIS SET OF DOCUMENTS IS PROPRIETARY BY NATURE. ANY USE, DISCLOSURE OTHER THAN THAT WHICH RELATES TO COVANTA MID-CONN., INC. IS STRICTLY PROHIBITED.

REVISIONS

NUMBER	DATE	REMARKS

MID-CONNECTICUT PROJECT MSW FLOOR REPAIR

MAXIM ROAD
 HARTFORD, CT.

PROJECT NO: 36937394
 DRAWN BY: MMM
 CHECKED BY: PJG
 DATE: 10/24/07
 CADD FILE: S003.DWG

MSW FLOOR REPAIR PLAN (STAGE I & 2)

S-003

1 MSW FLOOR REPAIR PLAN (STAGE I & 2)
 S-003

